

As the Forest Creek crew mows the green surrounds, they take all necessary steps to eliminate contaminating the Champion Bermudagrass greens. When cutting the surrounds, they will continue to have someone blow the clippings away until the greens are more established.

Hole #1



The fairway bunker on #3 is coming to life now that the edges have been sodded. Multiple areas were added to assist getting in and out of the bunker safely. Although slightly smaller in size, it remains an intimidating hazard!

Hole #3



The fairway landing zone on #11 is flagged for extensive drainage. The added drainage will greatly assist with more distance on your drives after a rain event!

Hole #11



Fairway drainage goes in the landing zone on #8 as well. I am happy to report that after 2 1/2 inches of rain last night, areas that have already received this type of drainage were dry as a bone this morning!

Hole #8



Hole #'s, 5, 6, 7, & 11

The McDonald and Sons crew cut new cart paths in various locations around the course. As you see in the pictures above, the new paths are much closer to either the teeing area or green than the original paths.